




## Input Connector and Protections




## RS485 to UART Converter




## Microcontroller



## Step-Down 3.3V




## Sensors



## Breakaway Tabs and Fiducials



## Testpoints



## Additional Silkscreen



Title: **Wired RHT Sensor**

Rev: 1

Sheet Name: /

Author:

File: rht\_wired\_sensor.kicad\_sch

Date:

KiCad E.D.A. kicad (6.0.6)

Size: A4

Sheet: 1/1