




## Input Connector and Protections




## Step-Down 3.3V




## RS485 to UART Converter



## Sensors




## Microcontroller



## Breakaway Tabs and Fiducials



## Testpoints



## Additional Silkscreen



**Title: Wired RHT Sensor**

Rev: 1

Sheet Name:

Author:

File: rht\_wired\_sensor.kicad\_sch

Date:

Sheet: 1/1

Size: A4

KiCad E.D.A. kicad 7.0.9-7.0.9-ubuntu22.04.1